

# Correct handling of metal working fluids

**1**

Do not throw debris into the cutting fluid



**2**

Skin protection  
Apply barrier cream before work



**3**

Coolant mixing:  
add concentrate to water



**4**

Check concentration  
prior to topping up

